

SlateTool v3.41 Build 20827 Release Notes

- Fixes the issue of building a wiresheet when there is a space in the windows username. The build looked like it was successful, however the files necessary for adding the project were not generated.

SlateTool v3.41 Build 20826 Release Notes

- Includes the latest web editor. See Web editor V1.2.38 release notes for details

SlateTool v3.41 Build 20819 Release Notes

- Supports Slate Firmware release 3.33
- Fixed issue where BACnet duplicates had been created in past releases of the tool. The duplicate BACnet object IDs will be renumbered after rebuilding the wiresheet this too revision.
- Fixed issue allowing duplicate IDs for BACnet Network Visibility
- Restored duplicate device menu item in the AXTool allowing user to create a duplicate of wiresheet
- Fixed issues with stale data when using the Annunciator and Limit Wizards in the AX tool
- Improved Modbus resequencing feature
- Improved import for language files
- Fixed issue with multi-line language string import
- Added feature that shows resources used in a wiresheet application. Results can be found in file SlateFBData.txt after building wiresheet in the AX Tool
- Fixed issue where the Module Selection page sometimes would not launch
- Fix Limit wizard to correctly show new R and S types of TC when setting up an Input
- Fixed issues that occurred at times starting Slate web editor
- Fixes error message displayed while installing: "This action is only valid for products installed"
- Improved error message regarding corrupted SLATE directory
- Includes the latest web editor with additional widgets and improvements. See Web editor V1.2.37 release notes for details